

National Aeronautics and  
Space Administration  
**John F. Kennedy Space Center**  
Kennedy Space Center, FL 32899



Reply to Attn of: SA-C

July 8, 2008

TO: Lyndon B. Johnson Space Center  
Attn: EA3/T. Martin

FROM: SA-C/Chairman, Ground Safety Review Panel

SUBJECT: Review of the Alpha Magnetic Spectrometer – 02 Helium Venting Analysis

The subject analysis (document # ESCG-4390-08-SP-MEMO-0017, dated 5/15/08) has been reviewed by the Ground Safety Review Panel (GSRP). The GSRP understands and accepts the analysis; however, the GSRP will not formally accept it until the subject is discussed as an agenda item at the AMS-02 Phase II Ground Safety Review, and is sufficiently documented in the Ground Safety Data Package Hazard Reports.

If you have any questions, you may contact Mr. Tom Tinsler at 321-867-3644.



Paul D. Kirkpatrick

cc:

NE-F3/M. Simpson  
NE-O-C/G. Hamilton  
NE-O-C/J. Mathis  
SA-B1/J. King  
SA-C/M. Smith  
SA-C1/J. Beach  
SA-C3/G. Hendricks  
SA-C3/S. Huet  
SA-C3/T. Tinsler  
TA-C2/M. Cardinale  
UB-G/T. Gill  
UB-I/D. Clark  
UB-I/S. Patel  
UB-R1/S. Bigos  
UB-R2/J. Hall  
UB-R3/J. Keifenheim  
HQ/OSMA/G. White

JSC/EA3/T. Martin  
JSC/ESCG/JE-1SA/E. Harvey  
JSC/ESCG/JE-4EB/M. Fohey  
JSC/ESCG/JE-4EB/L. Hill  
JSC/ESCG/JE-4EB/J. C. Tutt  
JSC/NE141/V. Berend  
JSC/NE141/G. Dawson  
JSC/NE141/D. Moreland  
JSC/OE/N. Vassberg  
JSC/OE/S. Wolf  
Boeing/721S-S210/K. Page  
Boeing/721S-S215/P. Lintereur  
Boeing/721S-S243/J. Degano  
Boeing/721S-S245/J. Balzer  
Boeing/721S-S280/M. Kinslow  
USK-291/R. Bond  
USK-291/D. Kotz